



VW 8422

REPARO DO DIFERENCIAL (AÇO)

DIFERENCIAL REPAIR STEEL (1987..01)
REPARACION DIFERENCIAL ACERO



.= 5013

94.405.519 7.90/7.110/8.140 Ø26 Ø57 e1,5 Ø62,8 Ø95 e1,5

VW 8424

REPARO DO DIFERENCIAL (AÇO)

DIFERENCIAL REPAIR STEEL (1994...98)
REPARACION DIFERENCIAL ACERO



.= 5072

BE2Y-4230-A VW 8.140 Ø29,2 Ø54,3 e1,0 Ø54,4 Ø82,85 e1,0

VW 9617

REPARO DO DIFERENCIAL (AÇO) TINKÃO

DIFERENCIAL REPAIR STEEL **Braseixos 345**
REPARACION DIFERENCIAL . = 5036



13.130 (81 / 87) D-900/950 (1979/85)

7.323.442 13.130(1981/87) Ø27,6 Ø61,4 E1,5 Ø67,7 Ø103,8 E1,5

VW 9238 ... 9239

ROLETE DO PATIM

BRAKE SHOE BRAKE ROLLER
ROLETE PATIN DE FRENO DE AIRE



TE-3.607.037 9239 17.210 STD Ø31,8 C58

2RP-607.037 9238-32 17.210 Ø32,0 C58

2RP-607.037 9238-35 17.210 Ø35,0 C58

2RP-607.037 9238-38 17.210 Ø38,0 C58

2RP-607.037 9238-40 17.210 Ø40,0 C58

2RP-607.037 9238-42 17.210 Ø42,0 C58

2RP-607.037 9238-45 17.210 Ø45,0 C58

VW 9005

SUPORTE DO CARDAN

CARDAN SUPPORT
SOPORTE CARDAN



TE-3.521.209 VW 14.140 L1= 232 L2= 58,5 ALT= 148